

## **Tagnite Production Technician III**

### **RESPONSIBILITIES:**

In addition to Tagnite Production Technician Level I and II, Production Technician Level III (TPT III) shall qualify through testing and training for working with high voltage hand held processes, (i.e. Brush Tagnite). TPT III shall become a certified applicator of brush Tagnite per established policies and standards. TPT III shall maintain certification through annual performance testing per the standards.

### **DUTIES:**

- Apply Brush Tagnite as required by the standards.
- Apply Brush Tagnite to touch-up any nicks, scratches, or dings prior to paint.
- Practice proper rinsing of parts using hot water using provided brushes.
- Practice proper Drying of parts using blowers, solvents and heated drying shelves.
- Use appropriate techniques to prevent water spotting, staining, transfer marks and other flaws caused by improper handling of wet parts.
- Assist other departments presenting parts for Brush Tagnite repairs.

### **TRAINING PERIOD:**

- 90 Days
- Must pass drug/alcohol test
- Must pass background check

### **REQUIRED DOCUMENTS:**

- Resume
- Company job application
- I-9

**REPORTS TO:** Tagnite Production Manager